

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Document Information

Location: Body BIW - Floors

Topic: Wind noise

Condition: Primarily at high speed

Diagnostic Trouble Codes: N/A

Measure

In the event of a customer complaint for wind noise and/or vibration when driving at high speed, raise the vehicle on the lift and inspect the engine floor.

If the floor is distorted as shown in the picture below, remove the floor and repair the deformed area of the floor.



In addition, further inspection is required at the inner engine floor surface as there may be contact between the floor and the fuel tank strap, see picture below.



Parts Information

N/A

Attachments

N/A

KA Update Information

21/04/2021 KA Review

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.