


# TECHNICAL TOPICS

## POWERTRAIN



<p><b>Engine Speed Stability</b></p> <p><u>Customer Complaint:</u></p> <ul style="list-style-type: none"> <li>There was a flashing D when slowing to a stop.</li> </ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> <li>Various contributing factors have been identified to improve idle quality.</li> </ul> <p><u>Status:</u></p> <ul style="list-style-type: none"> <li>Complete primary and secondary diagnosis for any DTCs that are stored.</li> <li>If no DTCs are stored, or if no other obvious root cause is identified, complete a PCM software update with Pathfinder 324 (released March 31, 2021) or later.</li> <li>Updated work instructions in the <b>TOPIX WSM section 303-14B: Electronic Engine controls – Ingenium I2 2.0L Petrol &gt; Diagnosis and Testing</b> will be published shortly.</li> </ul>	<p>19MY – Onward Discovery Sport, RR Evoque, RR Velar, Defender, RR/RR Sport PHEV, XE, XF, F PACE, F TYPE, E PACE equipped with AJ20P4</p> 
---	---

