



SERVICE BULLETIN

Classification:	Reference:	Date:
RS14-014	NTB14-096	October 13, 2014

2015 FRONTIER, XTERRA AND ARMADA; DIAGNOSIS AND REPAIR PROCEDURE FOR B00A0 DTC'S

APPLIED VEHICLES: 2015 Frontier (D40)
2015 Xterra (N50)
2015 Armada (TA60)

SERVICE INFORMATION

If DTC **B00A0** (OCCUPANT CLASSIFICATION SYSTEM CONTROL UNIT) is set as current in the Air Bag Diagnosis Sensor Unit:

- Follow the "DTC/CIRCUIT DIAGNOSIS" procedure for DTC B1017-B1022 (OCCUPANT SENS C/U) to repair the vehicle.

Refer to the Electronic Service Manual (ESM) section **SRC – SRS Airbag Control System** for procedure.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.