

Classification:

EL16-012

Reference:

ITB16-010

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Date:

March 2, 2016

2015 QX60; ELECTRICAL SYSTEM(S) IMPROPER OPERATION AFTER OPENING OR CLOSING A DOOR

APPLIED VEHICLES: 2015 QX60 and QX60 Hybrid (L50)

IF YOU CONFIRM:

Any one or a combination of the following after opening and/or closing a door (as it applies):

- The auto headlights do not time out after the ignition is set to the OFF position.
- The interior lights do not come ON.
- The Vehicle Information Display in the combination meter showing "door ajar" when the doors are closed.
- The Remote Engine Start feature is inoperative.

ACTION:

1. Remove, and then reinstall, the screw of all four (4) door switches.
2. Confirm whichever issue has been occurring is resolved.

NOTE: If the issue(s) is still not resolved, refer to ASIST and the appropriate Electronic Service Manual (ESM) for further diagnosis.


CLAIMS INFORMATION

Submit a Primary Operation (PO) type line claim using the following claims coding:

DESCRIPTION	OP CODE	SYM	DIA	FRT
R&I DOOR SWITCH SCREW	BX5QAA	ZE	32	0.2

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.