

# Technical Service Bulletin

PSS 90 Night vision assist message appears in the instrument cluster, DTC U110100 is stored in the night vision module

90 21 04 2063262/1 May 14, 2021.

| Model(s)   | Year        | VIN Range | Vehicle-Specific Equipment |  |
|--|-------------|-----------|----------------------------|--|
| A6, A7, S6,<br>S7, Q8, A8,<br>and Audi e-<br>tron quattro                  | 2019 - 2020 | All       | Night vision               |  |
| A6, allroad,<br>A8 PHEV,<br>SQ8, RSQ8,<br>and Audi e-<br>tron<br>Sportback | 2020        | All       | Night vision               |  |

#### **Condition**

#### **Customer states:**

- When using the night vision system, the message "Night vision assist: fault. Please contact service" is displayed in the instrument cluster.
- The night vision system does not work.

#### Workshop findings:

The following DTC is stored in the control module for the night vision system, J853 (address word 0084):

• DTC U110100 (Component protection active).

## **Technical Background**

A diagnostic feature is too sensitive.

### **Production Solution**

This bulletin will be updated when more information is available. A solution is currently under development.

#### **Service**

1. Clear the vehicle's DTCs.



## Technical Service Bulletin

- 2. Explain to the customer that a solution is forthcoming for the 2nd quarter of 2022 and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
- 3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links* >> *Service*), or through the Technical Assistance page in Elsa.

### Warranty

| vvarianty        |  |              |   |  |  |
|------------------|--|--------------|---|--|--|
| Claim Type:      | 110 up to 48 Months/50,000 Miles.  C10 for CDO Covered Vehicles - Verify Owner.                |              |   |  |  |
|                  | G10 for CPO Covered Vehicles – Verify Owner.   |              |   |  |  |
|                  | If the vehicle is outside any warranty, this Technical Service Bulletin is informational only. |              |   |  |  |
| Service Number:  | Number: 9081   |              |   |  |  |
| Damage Code:     | 0039   |              |   |  |  |
| Diagnostic Time: | GFF  | 0151 0000    | Time stated on<br>the diagnostic<br>protocol (Max 20<br>TU) |  |  |
|                  | Road test prior to service procedure   | No allowance | 0 TU  |  |  |
|                  | Road test after service procedure  | No allowance | 0 TU  |  |  |
| Claim Comment:   | As per TSB #2063262/1  |              |   |  |  |

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

#### **Additional Information**

All part and service references provided in this TSB (2063262) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may



# Technical Service Bulletin

these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.