

SSM75414 - L494 - Roof Rail Trim/Side Finisher Not Correctly Fitted Causing a Rattle
ROOF RAIL TRIM FITTING PROCEDURE

