

DTNA Solutions > Service Solutions > Freightliner
> SS 1033289 BHM Fault Code SPN 524249 / FMI 7

SS 1033289 BHM Fault Code SPN 524249 / FMI 7

BHM Fault Code SPN 524249 / FMI 7

Applicable Vehicles

M2, SD

Issue

BHM fault code 524249/7 is not documented in the M2 Workshop Manual and comes up with no description in Servicelink & Diagnosticlink.

Solution

524249/7 = MISSING SMART SWITCH

Troubleshoot same as documented fault code 6918/7.

Labels :

108SD114SD

Business Class M2

Electronics | Controls | Configuration | Communication | and Diagnostics

Freightliner

Add tags



12 Kudos

Comments



Talbert_Simonia

11-28-2017 12:21 PM

Thanks for the heads up Joe.



Chad_Budrow

12-12-2017 11:24 AM

Joe, do you know who would be in charge of making changes to the Workshop Manual?
There are other codes that fall in this same camp. For example:

Fault	New	Previous
Duplicate Smart Switch Fault	524250	6919
Extra Smart Switch Fault	524251	6920
Missing Smart Switch Fault	524249	6918

