

DTNA Solutions > Service Solutions > Freightliner > SS 1032989 – BHM Fault Code Changes

SS 1032989 – BHM Fault Code Changes

This is a republication of Service Solution 1032989. Please see the attached document to assist with the issue described below.

SS 1032989 – BHM Fault Code Changes

Applicable Vehicles

Applies to ALL units equipped with a BHM, and ONLY applies to SPNs reported from Source Address (SA) 33 on those units.

Symptoms

Different units may report the same root issue using a completely different SPN, but the same SA and FMI (e.g. Missing Smart Switch could be seen as fault code 33/6918/7, 33/524282/7 or 33/524249/7, depending on the age of the truck and the parameter loaded for fault reporting).

Issue

The original Bulkhead Module fault list dated back to 2003, but subsequent changes were made by the SAE to the standard that overlapped with ones currently in use on our products. In 2016, the fault codes in the overlap area were reassigned to other SPNs.

Labels :

108SD114SD

122SD

Business Class M2

Electronics | Controls | Configuration | Communication | and Diagnostics

Add tags

Attachments

