

# SERVICE BULLETIN 589: FUEL HOSE CLIP ALIGNMENT



## Notice Information

Ref	18566
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

**TOL NOTICE (US&CA) – May 18, 2021**

**TOL Ref. # 18566-SVC**

## SERVICE BULLETIN 589: FUEL HOSE CLIP ALIGNMENT

Triumph has released **Service Bulletin 589**. Internal investigations have identified the possibility of the fuel hose clip to cause damage to the fuel pump plate on the below models. Dealers are requested to realign the clip on the fuel hose as described in the procedure outlined in [Service Bulletin 589](#).

SB 589: Fuel Hose Clip Alignment				
Bulletin #	Models Affected	VIN Range		Markets
589	Bonneville T100 Bonneville T120 Bonneville T120 Black Bonneville Bobber Speedmaster Scrambler 1200 XE Scrambler 1200 XC Scrambler 1200 Steve McQueen Edition Speed Twin Street Scrambler Street Scrambler Sandstorm Street Twin Street Twin Goldline Thruxton RS	From AE5477	To AH3827	All Markets

Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory. Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on [www.triumphonline.net](http://www.triumphonline.net). **Motorcycles in the affected VIN range**

**found in Appendix A must be modified prior to delivery to the customer, or at the next visit to the dealership.**

Consult **Triumph Online (TOL) / Service Bulletin Page** (Bulletin # 589) or the attached **Service Bulletin 589** PDF for additional information including Fitting, Warranty Claim and Part Ordering instructions. Please also ensure that all relevant staff are up to date on these service instructions.

*Reminder:* Use the **“VIN Enquiry”** function within TOL (found under the **Service / Technical** drop-down menu) to search for any outstanding bulletins or recalls whenever a new motorcycle arrives or a Triumph owner visits your dealership.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.