

Technical Service Bulletin

94 Headlights may not turn off during daylight hours

94 21 39 2063739/1 June 23, 2021.

| Model(s) | Year | VIN Range | Vehicle-Specific Equipment |
|----------|-------------|-----------|----------------------------|
| All | 2018 - 2022 | All | Not Applicable |

Condition

When the light switch is in the "AUTO" position, the headlights are switched off later than expected or not at all during daylight.

Technical Background

When the sun is low in the sky (particularly during winter) and especially if the sun is also behind the vehicle (Figure 1), it is possible that the light sensor is within the vehicle's shadow (Figure 2).




Figure 1. Sun trajectory in relation to the vehicle's sensor.

In such cases, the sensor detects a lower ambient brightness than perceived by the driver. In this case it is possible that the headlights are not switched off as expected.




Figure 2. Close-up of the sensor's location.



Technical Service Bulletin

In addition to this, when the sky is clear/blue there is no cloud cover to reflect the sun's radiation back; this leads to a lower infrared value being measured at the sensor and intensifies the scenario described.

Production Solution

Not applicable.

Service



Note:

The only possible way to minimize the occurrence of this situation which complies with legal requirements is to change the switch-on point of the headlights to "late" in the MMI settings.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (2063739) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.