



Technical Service Bulletin

40 DTC B200000 stored in the front and/or rear stability control module

40 21 25 2061003/3 June 25, 2021. Supersedes Technical Service Bulletin Group 40 number 20-16 dated October 19, 2020 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8, S8	2020 - 2022	All	Stability control modules

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised header (Added Model Year) Revised <i>Warranty</i> (Removed test drive)
2	10/19/2020	Revised <i>Service</i> (Updated instructions)
1	10/06/2020	Initial publication

Customer states:

- Multiple active suspension malfunction messages appear in the instrument cluster.

Workshop findings:

The following DTC is logged in the front stability control module and/or the rear stability control module, J1152 and J1153 (address word 00D4 and/or 00D5):

- **DTC B200000** (Control unit fault).

Technical Background

Not applicable.

Production Solution

Not applicable.



Technical Service Bulletin

Service

If DTC B200000 is logged in the front stability control module and/or the rear stability control module, J1152 and J1153 (address word 00D4 and/or 00D5):

1. Record all battery history data from the data bus on board diagnostic interface, J533 (address word 0019).
2. Follow the ODIS test plan instructions for correction of the stored fault.

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	4024		
Damage Code:	0040		
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2061003/3		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2061003) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may



Technical Service Bulletin

these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.