

REFERENCE:	Nova Bus Manuals
SECTION:	16: Electrical System
RS N°:	MQR 7621-2204
EFFECTIVE IN PROD.:	N/A

APPLICATION DEADLINE: 2022JL01  
CLAIM REFERENCE NUMBER: WB-5117

SUBJECT:	Door alarm does not reset.
JUSTIFICATION:	The door alarm comes on when the air is released on the main door valve. The alarm does not reset/turn off even when the air is applied again.

LEVEL	DESCRIPTION	DIRECT CHARGES		TIME
		LABOUR	MATERIAL	
1	V-BEA reprogramming.	Nova Bus	Nova Bus	0.33 h
2	–	–	–	–

**MATERIAL**

QTY	PART N°	REV.	DESCRIPTION	REPLACES PART N°
<b>LEVEL 1</b>				
–	–	–	–	–
<b>LEVEL 2</b>				
–	–	–	–	–

**DISPOSAL OF PARTS**

REMOVED PARTS ARE:	DISCARDED	RETAINED	–
	–	–	

**REVISION HISTORY**

REV.	DATE	CHANGE DESCRIPTION	WRITTEN BY
NR	2021MA24	Initial release	Devanand

APPROVED BY:

Jean-Nicolas Fournier

Digitally signed by Jean-Nicolas Fournier  
DN: cn=Jean-Nicolas Fournier, o=Nova Bus, email=jean-nicolas.fournier@volvo.com, c=CA

PAGE 1 OF 3

\* Please contact your customer support manager to obtain the version of the software update

CLIENT	ORDER	ROAD NUMBER		VIN (2NVY/4RKY...)		QTY	PROGRAM	REV.
		FROM	TO	FROM	TO			
Houston - Texas	LB63	2050	2050	L82K2J9776708	L82K2J9776708	1	HOU4GE_M_00	F
Houston - Texas	LB72	2051	2069	L82K6J9776887	L82K4J9776905	19	HOU4GE_M_00	F
Houston - Texas	LC55	2070	2079	L82KXK9777378	L82K0K9777387	10	HOU4GE_M_00	F
Houston - Texas	LC91	2500	2501	L82J4L9777479	L82J0L9777480	2	HOU4DE_M_01	D
Houston - Texas	LC92	2502	2534	L82J8L9777601	L82J3L9777618	33	HOU4DE_M_02	B

**WARNING**

---

FOLLOW YOUR INTERNAL SAFETY PROCEDURES.

## PROCEDURE

**NOTE**

---

Program the V-BEA system using the program and revision indicated in the client listing or the one recommended by your customer support manager. See **section 16: V-BEA (VOLVO BUS ELECTRONIC ARCHITECTURE)** of the Nova LFS maintenance manual for the programming procedure.

