

Special Service Message

NOTE: A Special Service Message is a formal communication issued by Jaguar and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Jaguar technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 75436 - Powertrain Control Module (PCM) displays some Diagnostic Trouble Codes (DTC`s) as Unknown

Models : E-Pace / X540

Engineer Howden Robert

Name :

Last 24 JUN 2021 13:24:05

Modified :

Category : Diagnostic Software/Hardware

Symptom : 000101 Diagnostic Concerns

Content :ISSUE:

Powertrain Control Module (PCM) displays some Diagnostic Trouble Codes (DTC`s) as Unknown DTC

- 1483776
- 1484288
- 1484032
- 1483520

This may cause some Applications within ECU Functions not to complete as expected and illuminate the Engine Management Warning Light (EML)

CAUSE:

The DTC`s are not contained within the PCM variant fitted to the Vehicle

PERMANENT CORRECTIVE ACTION:

This concern has been resolved with the release of **PATHFINDER version 335**. The manual patch will no longer be available to download and this SSM will be deleted in 7 days.

Deleted - for reference only