

# TECHNICAL TOPICS ELECTRICAL



<p>Post 21A Update Apple CarPlay Navigation Voice Guidance Not Heard</p>	<p>16 – 21MY E PACE, F PACE, I PACE, F TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport equipped with NGI</p>
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> <li>– Navigation voice guidance is not working with Apple CarPlay</li> </ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> <li>– Navigation voice guidance is not functional with Apple CarPlay on NGI software version 21A due to a conflict between Apple CarPlay and NGI software</li> </ul> <p><u>Status:</u></p> <ul style="list-style-type: none"> <li>– SSM 75416 (Land Rover) SSM 75415 (Jaguar) has been published and will be updated once a repair has been made available</li> </ul>	



PRINTED COPIES ARE UNCONTROLLED