

CAMPAIGN LAUNCH STATUS

H330 – 21MY I-PACE - HIGH VOLTAGE JUNCTION BOX (HVJB)



UPS2521-1B H330 –AC CHARGING MAY BE INOPERATIVE

AFFECTED MODELS	21MY I-PACE
CURRENT VOLUME AFFECTED	1 IN USA and 5 in Canada
REPAIR	Affected vehicles require a series of EV battery charging tests on either mode 2 or 3 AC chargers and also a DC charge. If the battery fails to charge and on completion of DTC diagnosis, it is possible the HVJB will require replacement.
REPAIR TIME	Between 0.1 hrs and 5.0Hrs + DIDO
TARGET CAMPAIGN LAUNCH	May 4th, 2021
Notes	USA vehicle is under JLR control. Canadian units are held with Jaguar Brampton, Langley, Victoria, West Island and JLR Canada Service.

