SSM 49979 - 2021 Bronco - Big Bend And Outer Banks - Whistle From Front Hood Area

Some 2021 Bronco vehicles equipped with Big Bend and Outer Bank trim levels may exhibit a whistle noise originating from the front of the hood area when traveling at speeds above 30 mph (50 Km/h). If the whistle noise can be eliminated by taping off the gap between the hood and grill opening, this condition may be due to the hood seal design. Hood seal replacement will not resolve this condition. Inform customers that they can continue to drive the vehicle and Ford is currently working to release an improved seal design that will be available in October2021. Follow up with the customer to schedule an appointment once OASIS confirms part availability.

APPLICABLE VEHICLES 2021 TRUCK: G1 U725N BRONCO 2021 TRUCK: G1 U725N BRONCO