

TECHNICAL TOPICS ELECTRICAL



<p>Pivi IP 30.2 Release</p> <p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> - Request for software update shown on touchscreen <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> - Pivi IP 30.2 SW Update has been released as part of SOTA release 2.1.0 <p><u>Status:</u></p> <ul style="list-style-type: none"> - Pivi IP 30.2 Release will contain software improvements for: <ul style="list-style-type: none"> - Audio Distortion - Bluetooth improvements for iPhone & iOS 14 - Loss of audio - Pivi screen distortion when selecting certain Apps - Pivi screen dimming, backlight brightness changes - "No SIM detected" error message - Additional improvements are detailed in release notes (TOPix: Documents>>Software) 	<p>20-21MY L663, 21MY Discovery Sport, Discovery, Evoque, Velar, F-PACE, E-PACE, I-PACE, XF, Range Rover, Range Rover Sport</p>  
--	---



PRINTED COPIES ARE UNCONTROLLED