

CAMPAIGN LAUNCH STATUS

H352 and N578 CSP CAMPAIGNS – NO-START



CSP CAMPAIGN H352 & N578 - ENGINE NO-START

AFFECTED MODELS	21MY F-PACE, RR EVOQUE, DISCOVERY SPORT, DEFENDER, RR VELAR
VOLUME AFFECTED	3685 USA 66 CAN
<p>SUSPENDED</p> <p>Affected vehicles may experience a no-start due to a CANBUS repair. The repair can be performed by the Body control module and the instrument cluster. A software update will require a software update to the instrument cluster module.</p>	
REPAIR TIME	0.2 hrs + DIDO
CAMPAIGN LAUNCH	July 15 th 2021
Notes	189 unsold units



PRINTED COPIES ARE UNCONTROLLED