



Warranty Policies and Procedures Bulletin

Audi Warranty

Number: AWA-21-06

Subject: Intake Manifold Ext Warranty

Date: Aug 11, 2021

Dealers: U.S., Puerto Rico

This document modifies the Audi Warranty Policies and Procedures Manual.

Effective Reception Date: August 11, 2021

The following Intake Manifold limited warranty extension is applicable for certain Audi vehicles. Affected vehicles may include:

- Certain 2013 Model Year Audi A3 2.0L TFSI Vehicles

Note: This extension only applies to specific vehicles identified with Warranty Key U47.

To determine if a vehicle is eligible for this extension, check in the VIN in ElsaPro >> Vehicle Data. If the limited warranty extension is applicable to the vehicle, the “Warranty Key” section of the “Vehicle Data” screen in ElsaPro will be populated with Warranty Key U47.

Intake Manifold Limited Warranty Extension

For applicable vehicles, the New Vehicle Limited Warranty will be extended to cover repair or replacement (by an authorized Audi dealer) of a malfunctioning Intake Manifold during a period of 10 years or 120,000 miles, whichever occurs first, from the vehicle’s original in-service date.

The vehicle’s original in-service date is defined as the date the vehicle was delivered to either the original purchaser or the original lessee; or if the vehicle was first placed in service as a “demonstrator” or “company” car, on the date such vehicle was first placed in service.

What is Covered?

The limited warranty extension will be subject to the terms and conditions of the original applicable New Vehicle Limited Warranty (other than the extended time/mileage period) and will include the Intake Manifold and any parts and labor necessary to perform the repair. It will apply to all vehicles irrespective of whether the vehicle has been repaired on or before the effective date.

Damage resulting from outside influences, such as but not limited to, abuse, alteration or modification, a collision or crash, vandalism and/or other impact is excluded and not covered under the extended warranty. Repair or replacement under this extended warranty must be performed by an authorized Audi dealer.

Please be aware that other conditions (unrelated to the issue described in this extension) may cause the Malfunction Indicator Lamp (MIL) to come on. Customers should be prepared to cover the diagnosis and repair costs associated with these other, unrelated conditions.



Warranty Policies and Procedures Bulletin

The MIL is part of the on-board diagnostic system. Please refer to the owner's manual for additional information about the MIL. In some locales, an illuminated Malfunction Indicator Lamp could cause the vehicle to fail an IM emissions inspection, and the vehicle registration application could be denied.

Certain states have voluntarily adopted California-mandated emissions warranties only for vehicles equipped to meet California's Partial Zero Emissions Vehicle (PZEV) emissions requirements. These vehicles can be identified by inspecting the Vehicle Emission Control Information Label located under the hood. Because of this, the owner of a vehicle equipped to meet California's PZEV emissions requirements living in one of these states may have warranty rights that exceed the extended warranty offering described in this bulletin. Owners should refer to the warranty information that came with their vehicle for additional details as to whether or not this applies to their vehicle.

Transferability

The warranty, as extended, is fully transferable to subsequent owners.

Vehicle Eligibility

To determine if a vehicle is eligible for this extension, check in the VIN in ElsaPro >> Vehicle Data. If the limited warranty extension is applicable to the vehicle, the "Warranty Key" section of the "Vehicle Data" screen in ElsaPro will be populated with Warranty Key U47.

Vehicles with the totaled status are excluded from coverage under this Limited warranty extension.

Claim Processing

For the Intake Manifold Limited warranty extension:

Claim Type: 110
Service Number: 2447
Warranty Key: U47

Questions or Concerns

Contact Audi Warranty at 866.677.2834 or AudiWarranty@audi.com with questions or concerns related to this limited warranty extension.