# **Technical product information**

Topic	ic Infotainment screen turns red sporadically				
Market area	Bentley: worldwide (2WBE),Hongkong-Macau (5HK)				
Brand	Bentley				
Transaction No.	2055846/5				
Level	EH				
Status	Approval				
Release date					

#### New customer code

Object of complaint	Complaint type	Position
information, navigation, communication, entertainment -> radio, navigation, MMI, hard drive device functions	functionality	
information, navigation, communication, entertainment -> instrument cluster, displays, display panels	functionality	

# Vehicle data

### **New Continental GT and New Continental GTC**

#### Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S3*	2018	Е		*	*	*
3S3*	2019	Е		*	*	*
3S3*	2020	Ε		*	*	*
3S3*	2021	Е		*	*	*
3S3*	2022	Ε		*	*	*
3S4*	2019	Е		*	*	*
3S4*	2020	Е		*	*	*
3S4*	2021	Ε		*	*	*
3S4*	2022	Е		*	*	*

# **New Flying Spur**

#### Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
ZG2*	2020	Е		*	*	*
ZG2*	2021	Е		*	*	*
ZG2*	2022	E		*	*	*

# **Documents**

Document name master.xml

# Customer statement / workshop findings

Infotainment screen turns red sporadically (Figure 1)



Figure 1

### Technical background

A technical DISS query should be raised by the retailer to highlight the issue described is evident Refer to Measure section of this TPI

### Production change

Under investigation

#### Measure

Reset the Infotainment system as follows:

Press and hold the volume rotary switch (Figure 2) for 10 seconds



Figure 2

### **Customer information**

· Following the reset of the system the issue should not re-occur