

CAMPAIGN LAUNCH STATUS

H352 and N578 CSP CAMPAIGNS – NO-START



CSP CAMPAIGN H352 & N578 - ENGINE NO-START

AFFECTED MODELS	21MY F-PACE, RR EVOQUE, DISCOVERY SPORT, DEFENDER, RR VELAR
VOLUME AFFECTED	3,685 USA 66 CAN
REPAIR	Affected vehicles may experience a no-start due to a CANBUS communications concern between the Body control module and the Instrument cluster. All vehicles will require a software update to the instrument cluster module.
REPAIR TIME	0.2 hrs + DIDO
CAMPAIGN RE-LAUNCH	Sept 22nd, 2021
Notes	When re-launched, affected VIN will flag open in the warranty portal campaigns section.



PRINTED COPIES ARE UNCONTROLLED