


TECHNICAL TOPICS

ELECTRICAL



<p>2017 Model Year WiFi networks not found</p>	<p>2017 L405, L494, X760, X761, X351, L550, L538 equipped with TCU2</p>
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> - Wi-Fi networks unable to be found when attempting SOTA in the workshop environment <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> - JLRNA has been made aware of some retailers who may be experiencing an issue with 2017 model year vehicles when attempting to find a wifi network in the workshop environment - The workaround for this issue is to remove the vehicle from the workshop environment and away from retailer network range. - Once out of the retailer network range, the vehicle will find wireless networks, such as a mobile hotspot. <p><u>Status:</u></p> <ul style="list-style-type: none"> - Please submit an EPQR for any vehicles that are experiencing this concern. 	



PRINTED COPIES ARE UNCONTROLLED