



Preliminary Information

PIP5816A P0300 Setting After Bulletin 21-NA-154 Was Performed

Models

| Brand: | Model: | Model Years: | VIN: | | Engine: | Transmissions: |
|-----------|-----------|--------------|------|-----|----------|-----------------|
| | | | from | to | | |
| Chevrolet | Silverado | 2021 | All | All | 5.3L L84 | 10L80 RPO (MQB) |
| GMC | Sierra | 2021 | All | All | 5.3L L84 | 10L80 RPO (MQB) |

| | |
|----------------------------|---|
| Involved Region or Country | United States, Canada, Mexico, Middle East, Chile, Paraguay, Uruguay, Thailand. |
| Condition | A customer vehicle may have a concern of a P0300 setting after bulletin 21-NA-154 has been performed. |
| Cause | Unknown Engineering is looking into this concern. |

Correction:

The calibration has been released for this concern, please reference back to [21-NA-154](#).

Note: This is only for vehicle listed above with 5.3L L84 and 10-speed MQB

Version History

| | |
|----------|--|
| Version | 2 |
| Modified | 07/30/2021 - Created on. 09/27/2021 - Updated Correction Section. |



GENERAL MOTORS