TECHNICAL TOPICS BODY/CHASSIS





Air Conditioning System Inoperative (Electric A/C Compressors Only)

19 – 22MY I-PACE, Range Rover, RR **SPORT**

Customer Voice:

A customer may report that the air conditioning system is not cooling the vehicle cabin properly.

Technical Description:

On PHEV – EV model variants with an electric air conditioning compressor only, may not operate due to a fault with the Low Suction Pressure/Temperature sensor that does not set a related DTC in the HVAC module.

Status:

- SSM 75541 (Jaguar) and 75540 (Land Rover) has been published to provide diagnostic guidance.
- Please refer to the relevant SSM should a customer express a concern.









