

TECHNICAL TOPICS

BODY/CHASSIS



12-22MY RR Evoque, 14-22MY RR Sport, 15-22MY Discovery Sport, 17-22MY Discovery, 18-22MY RR Velar, 20-22MY Defender, 17-22MY F-PACE, XF, XE, E-PACE 18-22MY I-PACE

Seat Recliner Motor Inoperative

Customer Voice:

- A customer may report that the power seat recliner does not operate.

Technical Description:

- This may be caused by a seat recliner motor that has failed.

Status:

- The front seat recliner motor has now been released as a lower level repair and the replacement procedures has been added to the TOPIx Workshop Manual.
- Please refer to Workshop Manual > Section 501-10 Seating > Removal and Installation > Front Seat Recliner Motor.
- The seat back frame no longer needs to be replaced to repair a failed seat recliner motor.
- Part numbers Land Rover = LR154977, Jaguar T2H52346

