

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Document Information

Location: Powertrain

Topic: Oil smoke from the exhaust

Condition: Intermittent/Permanent

Diagnostic Trouble Codes: N/A

Measure

McLaren Technical Support have developed a form to assist Retailers when diagnosing smoking from the exhaust.

It has been noted that oil smoking from the exhaust can be caused by oil entering the CCV circuit. This situation is possible if the correct oil filling procedure as per SIS has not been followed, or the engine has been previously overfilled with oil.

This form must be used as guidance in diagnosis, as well as supporting data if a Technical Request is required.

Below is a link to download the form which must be completed electronically and not printed and filled in by hand. Once complete, if a TR is found to be necessary, please ensure the form has been correctly filled in and added to the documents section when raising the TR.

Link to download Exhaust Smoke Diagnostic Checklist [HERE](#)

Parts Information

N/A

Attachments

N/A

KA Update Information

03/11/2021 - First Release

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.