

# TECHNICAL TOPICS ELECTRICAL



<p><b>Post 21A Update Apple CarPlay® Navigation Voice Guidance Not Heard</b></p> <p><u>Customer Voice:</u></p> <ul style="list-style-type: none"><li>- Navigation voice guidance no longer operational after latest NGI update</li></ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"><li>- NGI 21A software error causing loss of voice guidance when using CarPlay® applications</li></ul> <p><u>Status:</u></p> <ul style="list-style-type: none"><li>- 21B resolves this issue and is currently in queue for release to TOPIX</li><li>- Guided diagnostics has also been updated for this issue</li><li>- <b>SSM75416 has been published and will be updated once the software release has been completed</b></li></ul>	<p>2016 – 2021 Discovery, Discovery Sport, Evoque, Velar, Range Rover Sport, Range Rover, E-Pace, F-Pace, I-Pace, XE, XF, F-type, XJ with NGI</p> 
---	---



PRINTED COPIES ARE UNCONTROLLED