
Reference	SSM75623
Models	XE / X760 (P68685 → P68559) XF / X260 (Y90398 → Y90318)
Title	21MY/22MY (X760/X260) – Noise from R/H rear or water ingress into the luggage compartment.
Category	Body
Last modified	30-Nov-2021 00:00:00
Symptom	110000 Sealing

Content Issue:
Customer may report excessive road noise from the R/H rear of the vehicle and/or water ingress into luggage compartment.

Cause:
R/H rear quarter panel vent may not be installed correctly.

Action:
If this symptom is reported please carry out the following:

- Visually inspect the R/H rear quarter panel vent.
- If it is incorrectly installed, then replace with a new part.
- If it is correctly installed, then continue to investigate.

Thank you in advance for your assistance with this matter.

anBhdHRicnM7MjAyMS0xMj0wMjQzMzoxNjczNy4wNzZaOzE2NS4yMjUuNTYuMjJwOw==