

**** TECHNICAL INFORMATION NOTICE ****

DATE: November 10, 2021
TO: Mitsubishi Motors US & Puerto Rico Dealer Service and Parts Managers
RE: Photo Required Condition Requirement for Audio Amplifier
TIN NO.: TIN-21-54-005

.....

AFFECTED VEHICLES: 2022 Outlander

PURPOSE:

To notify dealer that photos must be submitted to the Photo Required Condition Center prior to replacement of the Audio Amplifier.

Please submit a minimum of 3 high resolution photos of the amplifier terminals, connector, and unit itself prior to replacing. Photos are required in order to gain approval for the replacement of this component.



Labor Operation Code	54501410
Part Number	8701A779

Note: Failure to submit quality photographs as instructed above will result in an investigation of the Warranty Claim and possible denial. Please follow all Warranty Policy and Procedure steps when submitting claims.