

GROUP	NUMBER	
Campaign	21-01-065H	
DATE	MODEL(S)	
November, 2021	Santa Fe (TMa)	

SUBJECT:

SUN VISOR RETAINER INSPECTION & REPLACEMENT (SERVICE CAMPAIGN T7C)

* IMPORTANT

*** Dealer Stock and Retail Vehicles ***

Dealers must perform this Service Campaign on all affected vehicles prior to customer retail delivery and whenever an affected vehicle is in the shop for any maintenance or repair.

When a vehicle arrives at the Service Department, access Hyundai Motor America's "Vehicle Information Screen (VIS)" via WEBDCS to identify open Campaigns.

Description: This bulletin describes the procedure to inspect, and if necessary, replace the sun visor retainer for certain 2021 – 2022MY Santa Fe (TMa) vehicles with Calligraphy trim and Obsidian Black interior (color code: NNB).

Applicable Vehicles: Certain 2021 – 2022MY Santa Fe (TMa) vehicles produced between 5/3/2021 – 8/31/2021 and equipped with Calligraphy trim and Obsidian Black interior (color code: NNB).

Parts Information:

Model	Part Number	Part Name	
Santa Fe (TMa)	85210-S2520NNBQH	SUNVISOR ASSY,LH	
	85220-S2520NNBQH	SUNVISOR ASSY,RH	

Warranty Information:

MODEL	OP CODE	OPERATION	OP TIME	CAUSAL PART	NATURE CODE	CAUSE CODE
	10DA31R0	Sun Visor Inspection	0.2 M/H	85210-S2520- NNBQH	A32	ZZ3
Santa Fe (TMa)	10DA31R1	Sun Visor Inspection & Replacement (One Side)	0.3 M/H			
	10DA31R2	Sun Visor Inspection & Replacement (Both Sides)				

NOTE 1: Submit Claim on Campaign Claim Entry Screen.

NOTE 2: If a part that is not covered by this Service Campaign is in need of replacement while performing this Service Campaign, and the affected part is still under warranty, please submit a separate claim using the same repair order. If the affected part is out of warranty, submit a prior approval request for goodwill consideration prior to performing the work.

NOTE 3: Sun visor(s) called back by the Warranty Technical Center (WTC) that do not match the specified symptom will be subject to charge back.

Service Procedure:

1. Flip the sun visor to the down position.




2. Pull down on the sun visor to inspect if the retainer is broken (approx. 5 lbf).

Repeat the inspection on the opposite side.



Excessive force may cause unnecessary damage.



If the retainer remains in place, no further action is required.



NOTICE

If the part is called back by the Warranty Technical Center (WTC) and does not match the specified symptom, the claim will be subject to charge back.

4. Refer to the shop manual for the sun visor replacement procedure:



5. The service procedure is now complete.

TSB #: 21-01-065H Page 2 of 2