



Technical Service Bulletin

PSS 91 MIB3: favorites, home address, and stored destinations are lost

91 21 55 2062266/4 December 8, 2021. Supersedes Technical Service Bulletin Group 91 number 21-42 dated October 13, 2021 for reasons listed below.

| Model(s) | Year | VIN Range | Vehicle-Specific Equipment |
|--|-------------|-----------|----------------------------|
| A4, S4, A4 allroad, A5, A5 Cabriolet, A5 sportback, S5, S5 Cabriolet, and S5 sportback | 2020 - 2022 | All | MIB3 |
| A6, A6 allroad, A6 Avant, S6, RS 6 Avant, A7, S7, RS 7, A8, S8, Q5, SQ5, Q7, SQ7, Q8, SQ8, RS Q8, RS 5, RS 5 sportback, Audi e-tron quattro, and Audi e-tron sportback quattro | 2021 - 2022 | All | MIB3 |
| A3, S3, Audi e-tron GT, and Audi RS e-tron GT | 2022 | All | MIB3 |

Condition

| REVISION HISTORY | | |
|------------------|------------|---|
| Revision | Date | Purpose |
| 4 | - | Revised header (Corrected Elsa display issue and added software) |
| 3 | 10/13/2021 | Revised header (Added Models and Model Years) Revised <i>Service</i> (Updated expected release date) |



Technical Service Bulletin

| | | |
|---|------------|--|
| 2 | 08/02/2021 | Revised <i>Service</i> (Updated expected release date) |
|---|------------|--|

Customer states:

- Last destinations, favorites, and home/work addresses are sporadically lost.

Workshop findings:

- The concern might not be reproducible at the dealership due to it happening sporadically.

Technical Background

A software bug can cause some user data to be lost on boot-up.

Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

Service

1. Explain to the customer that a solution is forthcoming for the 3rd quarter of 2022 and that no repairs are necessary at this point. A workaround procedure will become available by the end of 2021, by which time this PSS will be updated with that procedure.

Do not replace any components for this condition since this will not resolve the customer's concern.

2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*), or through the Technical Assistance page in Elsa.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (2062266) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes



Technical Service Bulletin

at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.