

## **SSM 50364 - 2021-2022 F-Super Duty - Illuminated ABS Warning Lamp - No Communication With ABS Module**

Some 2021-2022 F-Super Duty vehicles may exhibit an illuminated anti-lock brake system (ABS) warning lamp due to various diagnostic trouble codes or faults. If the ABS module does not respond to the Ford Diagnosis and Repair System (FDRS) scan tool during normal diagnostics, make sure all related connectors are fully seated. If no connector concerns are found, remove the FDRS scan tool from the vehicle and disconnect the vehicle battery cables for 10 minutes. Reconnect the battery cables and attempt to re-establish communication with the ABS module using the FDRS scan tool.

APPLICABLE VEHICLES  
2021 - 2022 TRUCK: FE P558N SUPER DUTY