



# Service Bulletin

Bulletin No.: 21-NA-091

Date: November, 2021

## INFORMATION

**Subject:** Information on Normal Rear View Camera Display Operation - Flashing Diamond - Spot - or UFO like Image on Rear View Camera Display


**This bulletin replaces PIT5799A. Please discard PIT5799A.**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CT4	2020	2020				
	CT5		2021				
	Escalade						
	Escalade ESV						
	XT4						
Chevrolet	Bolt EV	2020	2020	—	—	—	—
	Corvette		2021				
	Silverado 1500						
	Silverado 2500HD/3500HD		2022				
	Tahoe		2021				
	Suburban						
GMC	Sierra 1500	2020	2021				
	Sierra 2500HD/3500HD		2022				
	Yukon		2021				
	Yukon XL						


<b>Involved Region or Country</b>	North America, Europe, Uzbekistan, Russia, Middle East, Israel, Palestine, Brazil, Chile, Colombia, Ecuador, Paraguay, Peru, Japan, GM Korea Company, Cadillac Korea (South Korea), Thailand, Australia/New Zealand
<b>Additional Options (RPOs)</b>	Equipped with UVI, UVS or UV2
<b>Condition</b>	Some customers may comment on a flashing light present on the radio display when in Reverse and with the rear view camera on, usually is corrected by an ignition cycle.



5787270



5787272

	 <p style="text-align: right;">5787273</p>
<p><b>Correction</b></p>	<p>Please communicate to the customer that the rear view camera system and radio display are functioning as designed and this is a normal condition of their vehicle. Please share this information with the customer, including a copy of this bulletin.</p> <p>Technicians should verify that no other conditions are present and return the vehicle to the customer.</p>

<p><b>Version</b></p>	<p>3</p>
<p><b>Modified</b></p>	<p>Released April 13, 2021</p> <p>May 03, 2021 – Added the Cadillac XT4 and updated the Involved Region or Country section.</p> <p>November 17, 2021 – Added the 2022 Model Year to the Silverado 2500HD/3500HD and Sierra 2500HD/3500HD models.</p>

