

Subject: Engineering Information – Check Engine Lamp Illuminated on Driver Information Center (DIC), DTC P0607 Set

Attention: Proceed with this EI ONLY if the customer has commented about this concern AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard the PIE and proceed with diagnostics found in published service information. THIS IS NOT A RECALL — refer to the latest version of Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Envision	2021	2022	—	—	—	—
Cadillac	CT4						
	CT5						
Chevrolet	Corvette						

Involved Region or Country	North America
Condition	<p>Important: If the customer did not bring their vehicle in for this concern, DO NOT proceed with this EI.</p> <p>Some customers may comment that the Check Engine Lamp is illuminated on the Driver Information Center (DIC).</p> <p>Technicians may find DTC P0607 set.</p>
Cause	GM Engineering is attempting to determine the root cause of the above condition. Engineering has a need to gather information on vehicles PRIOR to repair that may exhibit this condition. As a result, this information will be used to "root cause" the customer's concern and develop/validate a field fix.

Correction

If you encounter a vehicle with the above concern, contact an engineer listed below for further instructions. If the case is within 160 km (100 miles) of the GM Technical Center in Warren, MI., engineering will go to the dealer. If outside that range, we will request a Field Service Engineer to come and collect data.

Contact Information

The Contact Information has been redacted.

Please include the following information if leaving a message:

- Technician name
- Dealer name and phone number
- Complete VIN and repair order (R.O) number

On the repair order, document the date and time the call was placed (even if the engineer was not reached).

If engineering is unable to return the call within one hour, proceed with diagnosis and repair based on information found in SI.

Warranty Information

If engineer was contacted or required information was provided, use:

Labor Operation	Description	Labor Time
4088288*	Engineering Information - Check Engine Lamp Illuminated On (DIC), DTC P0607 Set	0.2 hr

*This is a unique Labor Operation for bulletin use only.

Version	1
Modified	Released November 16, 2021