

## Rear entertainment system display flickers

Topic number	LI82.85-P-072788
Version	1
Function group	82.85 - Navigation and Communication systems
Date	8/3/21
Validity	Model series 223 with code 854
Reason for change	

### Complaint

The rear entertainment system displays may flicker (see attached).

Attachments	
File	Description
<a href="#">223 rear display flickerin- g.jpg</a>	Picture of rear display flickering complaint

### Cause

Display in right/left rear passenger compartment (A40/5 and A40/6) software.

### Remedy

Perform software update of both rear passenger compartment displays (A40/5 and A40/6).

Symptoms				
Communication/information > Entertainment > Screen/display > Miscellaneous				
Communication/information > Entertainment > Screen/display > Flickers				
Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note

## XENTRY TIPS

---

			53E04**	Please state the LI number in the warranty claim text
			53T04**	Please state the LI number in the warranty claim text
			53G00**	Please state the LI number in the warranty claim text
			53V00**	Please state the LI number in the warranty claim text