

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Document Information

Location: Electrical - Infotainment (AIS)

Topic: After replacing the Infotainment Head-Unit (HU) the Rear View Camera (RVC) and McLaren Track Telemetry (MTT) are displayed on the main menu when they are not fitted to the vehicle

Condition: Permanent

Diagnostic Trouble Codes: N/A

Measure

If after replacing the AIS Head-Unit (HU) you've noticed that RVC and MTT are available on the main menu of the IRIS display, you need to raise a Technical Request.

This is because the by default configuration of the unit from the supplier is not compatible with the configuration of the vehicle.

To change the configuration, we need to enable and disable both features within the HU configuration sequence. The reason a Technical Request is required, is because a special PIN is needed to enable the MTT application which can only be given by McLaren Technical Support. A remote support session will be arranged to perform the above sequence.

Parts Information

N/A

Attachments

N/A

KA Update Information

11/05/2021 - KA review

30/08/2021 - KA review Q2

23/12/2021 - KA review Q4

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.