

Reference	SSM75631
Models	F-PACE / X761
Title	21MY (X761) – 5.0 AJ133 SVR PCM Calibration Update
Category	Driveability
Last modified	03-Dec-2021 00:00:00
Symptom	611000 Hesitation/Stumble
Content	<p><u>Issue:</u> JLR is investigating an issue on F-Pace SVR where customers may experience limited acceleration during a kick-down event when fully depressing the accelerator.</p> <p><u>Cause:</u> A PCM calibration change to improve customer experience.</p> <p><u>Action:</u> If this symptom is reported and the PCM software part numbers are as per the list below, then please DO NOT attempt to take any further actions (this includes software updates/diagnostics). A new software calibration is due to be released by 05/01/2022 and a further update to this communication will be released.</p> <ul style="list-style-type: none">• MK8M-14C570-SAE• MK8M-14C570-SHD• MK8M-14C570-STD• MK8M-14C570-SCD• MK8M-14C570-SED• MK8M-14C570-SKC <p>Thank you in advance for your assistance with this matter.</p>

anBhdHRlcnM7MjAyMi0wMS0wNiQxOT01ODo0MC4zNTRaOzEzNi4yMjYyNDguODg7