

Date:

November 15, 2021

## DTC C1A17-49 OR C2580-49 STORED IN LASER/RADAR

NTB21-106

**APPLIED VEHICLES:** 2019-2022 Altima (L34) 2017-2022 Armada (Y62) 2022 Frontier (D41) 2018-2021 Kicks (P15) 2018-2022 LEAF (ZE1) 2016-2022 Maxima (A36) 2015-2022 Murano (Z52) 2016 Murano Hybrid (Z52H) 2014-2020 Rogue (T32) 2017-2019 Rogue Hybrid (T32H) 2017-2021 Rogue Sport (J11) 2020-2022 Sentra (B18) 2016-2021 Titan/Titan XD (A61) 2020-2022 Versa (N18)

## SERVICE INFORMATION

DA21-007

If DTC C1A17-49 or C2580-49 is stored in LASER/RADAR in the "PAST" column:

- Erase the DTC.
- DO NOT replace any parts.

If DTC C1A17-49 or C2580-49 is stored in LASER/RADAR in the "CURRENT" column. refer to the applicable ESM for instructions.

## **AMENDMENT HISTORY**

PUBLISHED DATE	REFERENCE	DESCRIPTION
November 15, 2021	NTB21-106	Original bulletin published

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.