



# Diagnostic Trouble Codes (DTC) P0069-64, P10EC-00, P0191-64 and P240F-00 In Different Combinations, Occurrences, And Time Stamps (Two To Four Codes), Possible Vehicle Derate - US17+OBD16, US17+OBD18 Emissions, Common Model Years 2018 And 2019



> Internal Content

**THIS SOLUTION SHOULD ONLY BE FOLLOWED IF TWO OR MORE OF THE LISTED FAULT CODES ARE PRESENT.**

**If only one of the DTCs is present on the DTC Readout, Guided Diagnostics should be followed as normal.**

**If a vehicle presents with a combination of between two and four of the relevant DTCs and the listed possible conditions and there are no other symptoms to indicate another issue:**

- Replace the external Engine Wiring Harness.

This solution will be updated when further information is available.

## Tags

- k33593604
- p0069-64
- p0191-64
- p10ec-00
- p240f-00
- p006964
- p019164
- p10ec00
- p240f00
- mack
- volvo

Live UI **ed links and attachments**

No links or attachments available

**Feedback**

NO LINKS OR ATTACHMENTS AVAILABLE

[Give feedback](#)

to help improve the content of this article