


Subject <b>Hybrid Radio - Error Message Pop-ups</b>		Market <b>USA</b>
Service Category <b>Audio/Visual/Telematics</b>	Section <b>Cellular Communication</b>	
Applicability <b>2022 Tundra</b>		

**APPLICABLE VEHICLES**

2022	Tundra
------	--------


**CONDITION**

Some 2022MY Tundra vehicles may experience one of the following pop-up messages if “Hybrid radio” has been enabled. Please follow the steps below to correct the condition.




**RECOMMENDATIONS**

1. Select the Gear Icon at the lower left of the screen.



2. Scroll down and select “Sound & Media”



Subject

**Hybrid Radio - Error Message Pop-ups**


Market

USA


Applicability

**RECOMMENDATIONS**


3. Select "Radio"



4. Toggle "Enable hybrid radio" to the off position.



5. Inform the customer that they may receive a "Weak signal" pop-up banner while driving, and to **NOT** select "Enable" as this will re-enable the setting and cause the pop-ups to occur.



**LINK REFERENCES**

This Tech Tip does not contain any link references