



# Preliminary Information

## PIT5852 Wipers Only Operate On One Speed

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Envision	2021	All	All	All	All

Involved Region or Country	North America
Condition	Wipers only operate on one speed and unable to change wiper speeds
Cause	Logic locked

Correction:

- Place wiper stalk switch to the off position.
- Disconnect the battery and wait at least one minute.
- Reconnect the battery and wait at least one minute.
- Clear all DTC's and wait at least one minute.
- Test for proper operation of the wiper system.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2086328	Disconnect Both Battery Cables For One Minute, Reconnect And Retest	.5 Hrs.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	09/16/2021 - Created on.

