



Preliminary Information

PIT5879 Service Safety Restraint System Message With B1A7A In History Or Right Rear Dome Lamp Not Working.

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Envision	2022	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may have a Service Safety Restraint System message accompanied by an airbag light on dash and the technician may find B1A7A in history. They may also comment about the right rear dome lamp not working.
Cause	Additional diagnostic features were added to the 2022 MY Overhead Console and the hardware / software design is inadequate to properly implement the diagnostics on the Passenger AOS Display LEDs. This software may also not be compatible with the level of rear dome lamps.

Correction:

Engineering is working on a solution, no not attempt any repairs at this time.

Additional SI Keywords

B1A7A

Version History

Version	1
Modified	12/22/2021 - Created on.

