

Mirror adjustment using switch group in driver's door not possible

Topic number	LI88.79-P-074287
Version	1
Function group	88.79 - Exterior mirrors - electrical system
Date	1/27/22
Validity	Model series 223, 206, 297
Reason for change	

Complaint

Adjustment of the outside mirrors using the driver's door switch group may not be possible or it is not possible to select the left or right outside mirror.

Cause

Possible software update needed to the switch group, "DSM_WM_D223 - S20/1 - Switch group 'power window assembly and outside mirror adjustment, driver's side'."

Remedy

Update to the latest software version for DSM_WM_D223 - S20/1 - Switch group 'power window assembly and outside mirror adjustment, driver's side'. If software is fully updated, further diagnosis is required.

Symptoms
Body > Door/Flap > Outside mirror > Mirror/Mirror adjustment > Operation malfunction

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note