




## Volvo Chassis - Model VN, Hood Release Cable Interference



### Internal Content

For vehicles affected by this issue, the corner of the air box will need to be modified:

Using an appropriate tool, cut the corner off of the air box. This will allow the cable to straighten out and prevent fatigue. A diagram with approximate dimensions can be found below. The blue section is the portion that will be trimmed off:



An example of an air box before and after being trimmed can be seen below:







 Tags [k65985310](#) [hood](#) [volvo](#)

 Live UI

## Related links and attachments

No content available



Feedback

[Give feedback](#)

to help improve the content of this article

Live UI