TECHNICAL TOPICS BODY/CHASSIS





Front Suspension Knocking Noise	17 - 21MY F-PACE, 18 – 21MY RR Velar
Customer Voice:A customer may report a noise from the front suspension when driving at low speeds with steering input applied.	
 Technical Description: Front suspension upper control arms are being replaced to address a suspension knock type noise concern, but root cause is not understood. Status: 	FP2 Bush
 Engineering is currently investigating this concern. SSM 75581 (Land Rover) and 75582 (Jaguar) have been published to support the investigation of this concern, requesting information to be provided in an EPQR submission. Please refer to these SSMs should a customer express a concern, retain any replaced parts and submit an EPQR with the requested data to support the investigation. Thank you for your support. 	FP7 Ball Joint







