

Technical product information

Topic	Rear Jacking point - Sill damage found during PDI
Market area	Bentley: worldwide (2WBE)
Brand	Bentley
Transaction No.	2065760/1
Level	EH
Status	Approval
Release date	

New customer code

Object of complaint	Complaint type	Position
whole vehicle -> accessories -> vehicle jack	component / consumables -> damaged	
body -> floor, body reinforcements -> sill	component / consumables -> damaged	

Vehicle data

Bentayga

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2020	E		*	*	*
4V1*	2021	E		*	*	*
4V1*	2022	E		*	*	*

Documents

Document name
master.xml

Customer statement / workshop findings

Damage found around the rear sill Jacking point during PDI (Figure 1)



Figure 1

Technical background

Refer to the Measure section of this TPI

Production change

-

Measure

In the event the issue is as described, please raise a technical DISS query ensuring clear photographs are attached

-

The operative MUST await feedback from *Product Support* before conducting any further work

Note to Product Support: The DISS query should be second levelled to the applicable Senior Engineer for review before responding to the retailer