



Technical Service Bulletin

GROUP ENGINE	NUMBER 22-EM-001H
DATE JANUARY 2022	MODEL(S) APPLICABLE VEHICLES BELOW

SUBJECT: ENGINE WARRANTY EXTENSION (TXXI)

Description: The warranty coverage for engine long block repair or replacement regarding engine damage or malfunction from connecting rod bearing wear has been extended to a Limited Lifetime Warranty and is valid for original and subsequent owners.

NOTICE

The warranty extension is limited to vehicles owned by individual consumers that have:

- Completed the Knock Sensor Detection System software update (Campaign 953) AND
- A check engine warning lamp illumination with DTC P1326 (Campaign T3G) OR
- An engine concern related to connecting rod bearing wear or damage.

Additional limitations apply. Please refer to: www.hmaenginesettlement.com

Please refer to Service Campaign T3G TSB # 21-01-066H (or latest version) for the engine inspection/replacement procedure.

Please refer to TSB # 21-01-067H (or latest version) for applicable part numbers and labor ops.

Applicable Vehicles:

Certain 2011-2014 MY Sonata (YF) vehicles with 2.0L Turbo and 2.4L engines
Certain 2015-2019 MY Sonata (LF) vehicles with 2.0L Turbo and 2.4L engines
Certain 2013-2018 MY Santa Fe Sport (AN) vehicles with 2.0L Turbo and 2.4L engines
Certain 2019 MY Santa Fe (TM) vehicles with 2.0L Turbo and 2.4L engines
Certain 2014-2015 MY Tucson (LM) vehicles with 2.4L engines
Certain 2018-2019 MY Tucson (TL) vehicles with 2.4L engines