



Bulletin No.: PIT5676B
Published date: 01/14/2022

Preliminary Information

PIT5676B Installation of Upfitter Auxiliary Switches (RPO 9L7)

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 4500HD, 5500HD, 6500HD	2019 - 2022	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	9L7
Condition	A Dealer or Upfitter may be looking for information on installing RPO 9L7 Upfitter Auxiliary Switches. The Upfitter Auxiliary Switches are located under the climate controls in the center of the dash.
Cause	Information not readily available in Service Information (SI.)

Correction:

Reference the latest version of GM Upfitter Integration Bulletin 148. The information can be found at <http://www.gmupfitter.com/> under the "Technical Bulletin" Tab and then "Show all bulletins."

Version History

Version	2
Modified	04/23/2019 - Created on. 01/06/2021 - Updated to add 2020 and 2021 Model Years 1/14/2022 - Updated to add 2022 Model Year

