



Preliminary Information

PIT5578D One Time use Heater Core Hose Clamps

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Equinox	2018 - 2022	All	All	All	All
GMC	Terrain	2018 - 2022	All	All	All	All

Involved Region or Country:	North America
Condition:	Heater core hose clamps may loosen after servicing the heater core inlet and outlet hose connections. This can cause a coolant leak into the vehicle interior.
Cause:	Heater hose clamps are for one time use only.

Correction:

The heater hose clamps are one time use and should be replaced whenever the connection is serviced.

Service Procedure:

Follow published service information in eSI.

Parts Information

Description:	Part Number:	Quantity:
Heater Hose Clamp	93190977	2

Version History

Version	5
Modified	07/26/2017 - Created on. 09/25/2017 - Update Model Information 01/27/2020 - Added 2019 and 2020 MY 01/29/2021 - Added 2021 MY 01/25/2022 - Added 2022 MY.



GENERAL MOTORS