



# Preliminary Information

## PIT5883B Information On Vehicles Built With Heated And Vented Seats Disabled / Heated Steering Wheel Disabled / Front Rear Park Assist Disabled

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2022	All	All	All	All
Buick	Encore GX	2022	All	All	All	All
Cadillac	CT4	2022	All	All	All	All
Cadillac	CT5	2022	All	All	All	All
Cadillac	Escalade Models	2022	All	All	All	All
Cadillac	XT4	2022	All	All	All	All
Cadillac	XT5	2022	All	All	All	All
Cadillac	XT6	2022	All	All	All	All
Chevrolet	Blazer	2022	All	All	All	All
Chevrolet	Camaro	2022	All	All	All	All
Chevrolet	Colorado	2022	All	All	All	All
Chevrolet	Corvette	2022	All	All	All	All
Chevrolet	Equinox	2022	All	All	All	All
Chevrolet	Malibu	2022	All	All	All	All
Chevrolet	Silverado	2022	All	All	All	All
Chevrolet	Suburban	2022	All	All	All	All
Chevrolet	Tahoe	2022	All	All	All	All
Chevrolet	Trailblazer	2022	All	All	All	All
Chevrolet	Traverse	2022	All	All	All	All
GMC	Acadia	2022	All	All	All	All
GMC	Canyon	2022	All	All	All	All
GMC	Sierra	2022	All	All	All	All
GMC	Terrain	2022	All	All	All	All
GMC	Yukon Models	2022	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	00G, 00R, 00V, 00Y and/or 00Z
Condition	This is an informational PI to bring awareness to certain vehicle options being disabled. Please be aware that some vehicles, identified by an RPO code, are built with the following option(s) disabled:

	Front and/or Rear Park Assist disabled - RPO's 00Z or 00Y Heated Steering Wheel disabled - RPO 00G Heated/Vented Seats disabled - RPO 00V or 00R
Cause	Parts shortage

**Correction:**

If you have a vehicle with any of these RPO's and a complaint that the option does not work do not perform any repairs at this time. Please reference the following GM Global Connect messages for more information:

Front and Rear Park Assist Disabled - Reference Number: GCUS-17-429 (Canada GCCA-9-4306)

Heated Steering Wheel Disabled - Reference Number: GCUS-17-425 (Canada GCCA-9-4310)

Heated/Ventilated Seats Disabled - Reference Number: GCUS-17-424 (Canada GCCA-9-4307)

**NOTE: On vehicles with Heated Steering Wheel Disabled, DTC U152B may be set, but it does not turn on any warning messages or lights.**

Additional SI Keywords

seat

Version History

Version	3
Modified	01/10/2022 - Created on. 01/18/2022- Updates to Condition and Model sections 01/26/2022 - Update to correction section to add Canada Global message numbers

